



Note:  
1. V = voltage  
2. I = current  
3. Total points of measurement= 10 Nos. of V and I  
4. AC and DC measurements are needed